








40.1040

UNIVERSAL MACHINE TAP FIRST CHOICE HSS-E



-  Macho de máquina multiuso HSS-E
-  Taraud machine universel HSS-E
-  Maschio a macchina universale HSS-E
-  Mашинные метчики общего применения HSS-E
-  Evrensel makina kilvuz ilk seçim HSS-E
-  优选通用丝锥HSS-E









M

Cod.	M	d1	P	d2	L1	L2	Prev. Hole Ø
401040M03	M3	3,00	0,50	3,50	56	10	2,50
401040M04	M4	4,00	0,70	4,50	63	12	3,20
401040M05	M5	5,00	0,80	6,00	70	14	4,20
401040M06	M6	6,00	1,00	6,00	80	16	5,00
401040M08	M8	8,00	1,25	8,00	90	17	6,80
401040M10	M10	10,00	1,50	10,00	100	20	8,50


UNIVERSAL MACHINE TAP FIRST CHOICE HSS-E

40.1046

-  Macho de máquina multiuso HSS-E
-  Taraud machine universel HSS-E
-  Maschio a macchina universale HSS-E
-  Машинные метчики общего применения HSS-E
-  Evřensel makina kilzuvuz ilk seřim HSS-E
-  优选通用丝锥HSS-E



THREAD LINE



M

Cod.	M	d1	P	d2	L1	L2	Prev. Hole Ø
401046M12	M12	12,00	1,75	9,00	110	24	10,20
401046M14	M14	14,00	2,00	11,00	110	26	12,00
401046M16	M16	16,00	2,00	12,00	110	26	14,00
401046M20	M20	20,00	2,50	16,00	140	32	17,50